VILLAGE OF POINT EDWARD Joint Health and Safety Committee - Workplace Inspections - Garage Area/Plant/Arena Public Works Hazard Rank: Class A Hazard -- High Risk Dec 173, 2019 S. Archort Date: Class B Hazard - Medium Risk Inspectors: Class C Hazard - Low Risk Applicable Number Hazard Rank Satisfactory REQUIRES IMMEDIATE tem WORKPLACE VISUAL INSPECTION ATTENTION COMMENTS Aisleways and Passageways a. Clear and unobstructed b. Sufficient width for all normal movement Access and Egress a. Routes and exits are clearly marked b. Exit signs are posted c. Exits are unobstructed/cleared of ice and snow d. Emergency Lighting for exit signs (if required) Floors and Stairways a. Free from loose material, debris, cords or cables b. Free from tripping hazards (oily, wet or badly worn) Stairways are well lit d. Stairways Stairway railing is mounted and secure Electrical Safety a. Electrical cords are in good condition b. Use of extension cords for temporary use only c. Receptacle faceplates are in place. d. Bulbs for normal lights and exit lights are working There are no tripping hazards Emergency lighting is in place/regularly tested g. Electrical wiring is properly concealed Electrical equipment being worked on is locked/tagged out Electrical panels are accessible and unobstructed Electrical switches in panels are labelled Fire Prevention and Protection Fire extinguishers are inspected monthly/annually b. Fire/emergency evacuation/escape plan is posted Flammable substances are properly stored. d. Paper and waste are properly and regularly disposed Storage Areas a. Heavy objects are stacked close to floor level b. Area is clean and accessible Materials are neatly and safely piled V d. Stepladders are available for materials on higher shelves V Storage shelves are not overloaded Stacks are stable and secure against stiding/collapsing g. Straps are fitted properly General Housekeeping a. Neat, clean and in good repair b. Washrooms are clean and sanitary 1 Food preparation areas are clean Chemicals a. MSDS sheets are available for chemicals being used. b. Chemicals are stored properly c. Chemicals are properly labelled

	P.W Dec 18, De	B	والمراجعة المراجعة ا			Form #02-10				
Item Number	WORKPLACE VISUAL INSPECTION	Satisfactory	Un-satisfactory	Not Applicable	REQUIRES IMMEDIATE ATTENTION	COMMENTS				
9	Compressed Gas Cylinders					(e.g. Propane, Oxygen)				
	a. Stored upright and secured against falling over			1/						
10	Fall Protection	ļ.,	<i></i>							
	a. Floor openings are covered/protected with guard rails b. Guard rails are adequately constructed and secured		<u> </u>							
11	Eye Wash Stations/Showers									
	a. Readily available/accessible	1	/							
-	b. Proper signs and instructions are available c. Flush for minimum 15 min. at comfortable temp. available	V								
	Emergency Rescue Equipment					TO PARAMATINA AND AND AND AND AND AND AND AND AND A				
	a. Adequate equiment is available/properly located	1	e ^r							
	b. Equipment is in serviceable condition									
13	Hand and Portable Tools									
<u> </u>	a. General condition of tools and cords is acceptable b. Guards/safety devices are not altered	V	ļ	-						
	c. Tools are properly stored when not in use	V	/							
	d. Tool storage is orderly	V				The state of the s				
14	Machine Tools/Guarding									
	a. General condition of tools and cords is acceptable	14								
 	b. Guards/safety devices are not altered c. Fixed guards are secured in position	1				J T T T T T T T T T T T T T T T T T T T				
	d. Hoses are colled when not in use	V	1							
	e. Extension cords out of walkways when not in use	_		-						
15	Spills and Leaks									
	Spills/Leaks are cleaned up as they occur Work orders issued promptly to fix leaks	1./	<u> </u>	0/	1					
 	c Spill response kit is available	1	-	12						
10	Waste Disposal									
16	a. Adequate number of waste containers is available		/	-						
	b. Separate containers are available for oily rags, etc.	V								
┢	c. Safe disposal facility for waste is used	1	_							
17	Mobile Equipment	<u> </u>	ļ							
_	Equipment is clean and orderly There are no loose or broken parts or tools	14	1	-						
	c. Safe loading/unloading area is used	1	/							
	d. Proper distance from overhead electrical	L								
18	Parking Areas/Site Access/Decks									
	Handrails/steps for entrance/decks in good condition	2								
\vdash	b. Parking lot is free of tripping hazards c. Parking area is well lit	15								
	d. Signs are in good condition	1								
	e. Yard is neat and orderly	1	1		1					
Dep	artmental Response: RESPONSES TO BE PROVIDED	WITH	IN 5	WOR	KING DAYS	FROM INSPECTION DATE				
		1	<u> </u>		J					
Comments and Recommendations:										
	3/2	7			·····	eal				
Insp	pector's Signature:	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			Managery report to the second					

VILLAGE OF POINT EDWARD

Satisfactory :	Hazard Rank	licable C	niga	Hazard Rank: Class A Hazard - High Risk Class B Hazard - Medium Risk Class C Hazard - Low Risk
		licable C	nisa	
		licable		Z Class C Hazara - LOW KISK
Satisfactory	ard Ran	<u>8</u>	l [
	Haz	Not Applicable	REQUIRES IMMEDIATE ATTENTION	COMMENTS
11				STOP DE
1				
-				Positive Contraction Contracti
	,			
10				
17				
	/			
1				
$\perp V$				
	<i>/</i>			
<u> </u>	/			
14	/			
 '				
+~				7.1111111111111111111111111111111111111
	,			
+6/			******	
+	7		-	
	,			
i/				The state of the s
V				
i/	/			
14				
+				
+				
				· · · · · · · · · · · · · · · · · · ·
10				
11/				7-7/4/4/4
1/				
11/				
\perp				
DED W	/ITHI	1 5 W	ORKING DA	YS FROM INSPECTION DATE
	I .	· · · · · · · · · · · · · · · · · · ·		
_T	····			

White copy - Health & Safety Coordinator (filed)

Yeitow copy - Department Head (respond and post)